Different Types Of Transformer



Prepared by : Sarbast S. Qadir Electrical Engineer

Content


Introduction	4
Based On Turn Ratio	5
Step Up Transformer	5
Step Down Transformer	6
Isolation Transformer	6
Based On Shape Of Core	7
Core Type	7
Sell Type	8
Berry Type	8
Based On Type Of Service	9
Power Transformer	9
Distribution Transformer	9
Instrument Transformer	9
Based On Number Of Phase	11
Single Phase Transformer	11
Three Phase Transformer	12
Auto Transformer	12
Based On Core Materials Used	13
Air Core Transformer	13
Iron Core Transformer	13
Ferrite Transformer	13

Based On Operating Frequency	13
Mains Frequency Transformer	13
Audio Frequency Transformer	13
High Frequency Transformer	13
On The Basis Of Application	14
Welding Transformer	14
Isolating Transformer	14
Constant Voltage Transformer	14
Based On The Insulation Used	14
Dry Type Transformer	14
Oil Immersed Transformer	15
On The Basis Of Cooling Method	15
Air Natural (AN) Cooling	15
Air Forced (AF) or Air Blast (AB) Cooling	15
Oil Natural Air Natural (ONAN) Cooling	16
Oil Natural Air Forced (ONAF) Cooling	16
Oil Forced Air Forced (OFAF) Cooling	17
Oil Forced Water Forced (OFWF) Cooling	17
On The Basis Of Winding Connection	18
Ster-Star Connection	18
Delta-Delta Connection	18
Delta-Star Connection	18
Star-Delta Connection	19
Open Delta or (V-V) Connection	19
Tee-Tee or Scott Connection	20

Introduction

There are different types of transformer classified on the basis of shape of core, type of service, number of phase etc. It is used in the electrical power system for different application, like generation, transmission, distribution, utilization of electrical Energy and in small electronic application also.

Different types of transformer are Step up, Step down, isolation, core type, shell type, berry types, Instrument X^{er}, Single phase and three phase X^{er}, Auto transformer, Welding transformer etc. All types of transformer is shown bellow in tree diagram.



TYPES OF TRANSFORMER

1.Based on Turn Ratio:

Types of Transformers Based on the Value of K or Number of turns. Transformation ratio is defined as the ratio of secondary voltage to primary voltage of transformer. That is V2 / V1 and it is denoted by 'K'.


Types are:

- 1. Step up
- 2. Step Down
- 3. Isolation Transformer.

1.1. Step up transformer:

If the number of turns in primary winding is less than secondary winding turns then this type of transformer is called as step up transformer. OR


The transformer having value of K > 1, this type of transformer is called as the step up transformer. We get higher secondary voltage as compared to the primary winding, hence its name is step up.



1.2. Step down transformer:

If the number of turns in primary winding is more than secondary winding turns then this type of transformer is called as step down transformer. OR


The transformer having value of K < 1 then it is called as the step down transformer. We get lower secondary voltage than the primary voltage, hence its name step down.1.2.



1.3. Isolation transformer

If the number of turns in primary winding is equal to the secondary winding turns then this type of transformer is called as isolation transformer. OR

The transformer having value of K = 1 then it is called as the isolation transformer. We get same secondary voltage as the primary voltage, hence its name isolation transformer.



2.Based On Shape of Core


On Shape basis there are three type of transformer classified as follow:

- 1.Core type
- 2.Shell type
- 3.Berry type

2.1 Core type

The structure of <u>core</u> of this transformer is in the form of a rectangular frame made from cold rolled grain oriented sheet steel (C.R.G.O.) with thin silicon steel laminations.


The primary and secondary windings are uniformly distributed on two adjacent limbs of the core. Both the windings are of cylindrical shape and they are arranged in a concentric manner the Low voltage (LV) winding is place near the core and high voltage (HV) winding is on over it.



2.2. Shell type

The construction of a <u>shell type</u> transformer shown in figure. The primary and secondary windings are placed on the central limb of the core. The high voltage and low voltage windings are arrange in sandwich type.


This type of core provides double magnetic circuit and it provides a better mechanical support and protection for the windings. The material used for making core is same as core type transformer.



Shell Type Transformer

2.3. Berry type

It is basically a shell type transformer structure but the name is related to the design like berry and its cylindrical shape. Berry type transformer has distributed magnetic circuits and more than two independent magnetic circuits. The core construction of berry type transformer magnetic core and cylindrical windings is shown in graphics from top view and side view given below.



3.Based on type of service

On Basis of type of service there are three type of transformer are

- 1) Power transformer
- 2) Distribution Transformer
- 3) Instrument Transformer

3.1. Power Transformer

Usually power transformer is used in transmission line to transmit hug amount of power with high voltage ratings. Typically the voltage range of power transformer is about from 33KV to 400KV or more (400 kV, 200 kV, 110 kV, 66 kV, 33 kV) and power range is greater than 200MVA. So its size and weight is much more than all other type of transformers.

3.2. Distribution transformer

Distribution transformer is used in distribution networks to distribute power coming from transmission line. Highest range of the distribution transformer is 11KV and lowest one is 230V. It mean the variation of this type of transformer voltage rating depending upon the application where it use, this range is 11 kV, 6.6 kV, 3.3 kV, 440 V, 230 V.

3.3. Instrument transformer


To measure high voltage like 110 kV or 220 kV and high value of current, it is not possible from safety point of view to connect a voltmeter or ammeter to a very high voltage and current range line. Also an instrument which will stand to such a high range its size is very large comparatively normal range meters.

In such cases special type of transformers is required and this transformers called as instrument transformer. They are classified in two categories, current transformer and voltage or potential transformer.

3.3.1. Current Transformer (CT)

If a large current carried by a conductor is to be measured, it is advice to avoid the direct connection of ammeter in this high current line, for this purpose a current transformer is used.

A current transformer (CT) is nothing but a coil wound on a core. The primary of C.T. carries the large current which is to be measured. The secondary winding is a low current winding, so the secondary of a C.T. is made up of large number of turns. The construction of a current transformer is shown in figure below.




Current Transformer (CT)

3.3.2. Potential Transformer (PT)

The potential transformer is second type of instrumentation transformer which is used to measure high ac voltage. The construction of a potential transformer is same as that of the normal transformer but difference is that potential transformer is always step down construction.

To measure high voltage, voltmeter is connected on low voltage side of transformer. The connection and construction of a potential transformer is shown in figure.




4.Based on number of phase

On the basis of number of phase there are three types of transformer are

- 1. single phase
- 2.three phase
- 3. auto transformer

4.1. Single phase transformer


The basic construction of a single phase transformer is shown in figure. It consists of two highly inductive coils called as winding of transformer wound on a core made up of iron or steel material. Winding connected to the supply called as primary side and it connected to the load called as secondary side. In single phase transformer input is single phase and output is also same.



4.2. Three phase transformer

The three phase transformers constructed, by using three single phase transformers or three winding on core in single transformer tank as shown in figure below.

In three phase transformers, windings are connected such that the three primary windings are placed in delta or star and similarly the secondary windings are also connected in star or delta depending upon the application of area.




Three Phase Transformer

4.3. Auto transformer

It is a special transformer which may be single phase or three phase. In normal transformer has separate primary and secondary windings, but in the autotransformer some part of the windings is common for the primary and secondary windings. The basic construction of an autotransformer is shown in figure below.

It consists of only one or three winding wound on a core which is laminated and a rotary movable contact for selecting the particular portion of the winding. The autotransformer can used as a step down or step up transformer.



5.Based on core material used

5.1. Air Core Transformer

This type of transformer consist of a hollow nonmagnetic core like plastic or paper and primary and secondary winding wound over it. This type of transformer the transformation ratio is less than one. Air core transformer generally used in high frequency application because there is no iron loss in it.

5.2. Iron Core Transformer

In iron core transformer laminated iron core is used. This is the commonly used type of transformer.

5.3. Ferrite core transformers

Core of this type of transformer is made up of ferrite material. These transformer is used for very high frequency application.

6.Based on operating frequency

6.1. Mains frequency transformer

These transformer is basically iron core shell type transformer and connected between ac main source and other device require ac or dc power. These transformer primary have more than two terminals and secondary winding have a centre tap.

6.2. Audio frequency (AF) transformers

The size of this type of transformer is very small and it used to mounting on PCB to design to operate over the audio frequency range of 20HZ to 20 KHz.

6.3. High frequency transformers


Core of this type of transformer is made of powdered iron or ferrite material. This transformer is also called as Intermediate frequency transformers (IFTs) or Radio Frequency transformer (RFTs).

7.On the basis of Application

7.1. Welding transformer

In welding process large current flow through the welding electrodes so that an arc is produced between the electrodes and work piece. Hence welding transformer is a transformer having a low current in primary side and high current secondary side winding.

So the welding transformer is always step down transformer with a large number of primary turns and a small number of secondary turns.



7.2. Isolation transformer

About isolation transformer discus previously.

7.3. Constant voltage transformers

This transformer gives constant voltage at output side. It is used to obtain stabilized voltage supply for sensitive equipment's

8. Based on the insulation used

8.1. Dry Type Transformer

This type of transformer does not contain any fluid cooling system, so the only cooling medium is Air only. Dry type transformers are commonly used for indoor applications where other types of transformer are considerable too risky.

8.2 Oil Immersed Transformer

In such type of transformer oil is used for cooling purposes. Using oil cooling system is better than dry type cooling. Generally this type of transformer is used for outdoor application with high ratings.

9.On the basis of Cooling Method

For the dry type transformers

- Air Natural (AN) Cooling
- Air Forced (AF) or Air Blast (AB) Cooling

For oil immersed type transformers

- Oil Natural Air Natural (ONAN) Cooling
- Oil Natural Air Forced (ONAF) Cooling
- Oil Forced Air Forced (OFAF) Cooling
- Oil Forced Water Forced (OFWF) Cooling

9.1. Air Natural (AN) Cooling


The air natural (AN) cooling is used in dry type, self-cooled transformers. In this method, the natural circulation of surrounding air is used for cooling of the transformer. The windings of the transformer are protected against the mechanical damages by a sheet metal enclosure. The air natural cooling is used for low voltage small transformers upto a few kVA.

9.2. Air Forced (AF) or Air Blast (AB) Cooling

The air forced (AF) cooling is used in the dry type, forced-air cooled transformers. In this method, a continuous blast of filtered cool air is forced with the help of a fan through the core and windings of the transformer for cooling. This method is used for cooling of the transformers upto 15 MVA

9.3. Oil Natural Air Natural (ONAN) Cooling

The oil natural air natural cooling is used in oil immerged type transformers. The most of the transformers of the medium and large ratings have their core and windings immerged in dielectric oil, which acts both as cooling medium and insulating medium.




The oil immerged transformers are enclosed in a sheet steel tank. The heat generated in the core and windings being transferred to the oil. The heated oil becomes lighter and rises to the top and the cool oil takes its place from the bottom of the transformer tank.

The heat of the oil is transferred to the walls of the tank by natural circulation of the oil and the heat is then transferred to the surrounding air through the natural radiation and convection. Hence, the oil gets cooler and falls to the bottom. Therefore, a natural circulation of oil takes place for the cooling of the transformer.

9.4. Oil Natural Air Forced (ONAF) Cooling


In oil natural air forced cooling of the transformer, the heat generated by the core and windings of the transformer is transferred to the walls of the tank and to the radiator through the natural circulation of the oil. Now, the forced air is directed over cooling elements (tank, radiator, tubes, fins etc.) of the transformer. Hence, the transformer is cooled by the natural circulation of oil and blast of air.



This method of cooling is suitable for the large transformers up to 60 MVA.

9.5. Oil Forced Air Forced (OFAF) Cooling


In this method of cooling, the heated oil is circulated from the top of the transformer tank to a heat exchanger and the blast of air is forced through the heat exchanger by turning on a fan. Then, the cool oil is returned to the bottom of the transformer tank.



This method of cooling is used for higher rating transformers like transformers which are used in substations and generating stations.

9.6. Oil Forced Water Forced (OFWF) Cooling

In the oil forced water forced cooling method, the heated oil is circulated from the top of the transformer tank to a heat exchanger where the pressurised water is used to separate the heat from the oil. The cool oil is then returned to the bottom of the transformer tank.




This type of cooling is mainly used for very large transformers with a 100 MVA ratings like at generating stations.

10.On the basis of Winding connection


10.1. Star-star connection

The primary winding of this type of transformer is connected in star and secondary also connected in star.




10.2. Delta-delta connection

The primary winding of this type of transformer is connected in delta and secondary also connected in delta. In delta connected winding neutral is not available.




10.3. Delta-star connections

The primary winding of this type of transformer is connected in delta and secondary is connected in star.




10.4. Star-delta connection

The primary winding of this type of transformer is connected in star and secondary is connected in delta.



10.5. Open delta or (V - V) connection

If we remove any one transformer winding of a delta- delta configuration, and a 3-phase supply is connected to the primary windings, then three equal 3-phase voltage are available at the secondary terminal as shown in the figure.



10.6. Tee-Tee or Scott connection

In this type of transformer primary is supplied by three phase and from secondary side get two phase output.

